

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

1533  
North  
> 1  
1.919 mi.  
10131 ft.

**MH 6778**  
**AVE P/WEST 9TH**  
**BROOKLYN, NY**

**NY Spills** **S104952132**  
**N/A**

**Relative:**  
**Higher**

**Actual:**  
**19 ft.**

**SPILLS:**

Name: MH 6778  
Address: AVE P/WEST 9TH  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0011201 / 2001-06-01  
Facility ID: 0011201  
Facility Type: ER  
DER Facility ID: 237950  
Site ID: 294030  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2001-01-14  
Investigator: JHOCONNE  
Referred To: Not reported  
Reported to Dept: 2001-01-14  
CID: 396  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2001-01-14  
Spill Record Last Update: 2001-08-14  
Spiller Name: Not reported  
Spiller Company: CON EDISON  
Spiller Address: 4 IRVING PLACE  
Spiller Company: 001  
Contact Name: MARK SCHLAGEL  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was O'CONNELL CON ED E2MIS REPORT 1-14-01 Found approx. 6oz. of dielectric fluid on dirt in MH. Fluid leaked from damaged 4w1w joint in structure. No sewers or waterways affected, no fire /smoke, no water in structure, no sump or sewer connection. Joint wrapped to stop leak. 1 soil sample taken. 0455hrs. LSN 01-00397 <1ppm Cleanup complete by double washing hole, debris removed, barrels picked up and tag removed. Repairs made on the joint. Liquids were removed using diapers and coagulent. Source of oil was leaking joint. Sump cleaned but not cemented. Incident closed."  
  
Remarks: "6 OZ SPILLED..SAMPLES TAKEN AND CLEAN UP PENDING. REF #135090"  
  
All Materials:  
Site ID: 294030  
Operable Unit ID: 833273  
Operable Unit: 01  
Material ID: 541523  
Material Code: 0541A  
Material Name: dielectric fluid  
Case No.: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material FA:	Petroleum
Quantity:	6.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported